OTPE VOS OUR DE LES

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
Yutaka TANAKA et al.) Examiner: H. Nguyen
Application No.: 09/897,930	:) Group Art Unit: 2851
Filed: July 5, 2001	:)
For: PROCESSING APPARATUS FOR PROCESSING SAMPLE IN PREDETERMINED ATMOSPHERE	:) August 24, 2004 :
U.S. Patent No. 6,750,946 B2	Certificate
Issued: June 15, 2004	; AIIG 3 0 2004
	of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and
Trademark Office due to an error which appears in the printed patent as a result of Patent and
Trademark Office mistake and mistakes of a minor nature which are not the fault of the Patent
and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

08/25/2004 SSESHE1 00000120 6750946

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC_MAIN 174285v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,750,946 B2

: June 15, 2004 DATED

INVENTOR(S): Yutaka TANAKA et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 4, "load-jock" should read -- load-lock --.

OLUMN 11:

Line 49, "the exposure" should read -- an exposure --. Line 50, "comprising" should read -- comprising: --.

COLUMN 12:

Line 61, "comprising" should read -- comprising: --.

COLUMN 14:

Line 6, "comprising" should read -- comprising: --.

COLUMN 15:

Line 9, "the exposure" should read -- an exposure --. Line 10, "comprising" should read -- comprising: --.


MAILING ADDRESS OF SENDER:

PATENT NO. 6,750,946 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

 \Rightarrow __





IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
Yutaka TANAKA et al.) Examiner: H. Nguyen
Application No.: 09/897,930) Group Art Unit: 2851
Filed: July 5, 2001	·)
For: PROCESSING APPARATUS FOR PROCESSING SAMPLE IN PREDETERMINED ATMOSPHERE	. August 24, 2004 :
U.S. Patent No. 6,750,946 B2) :
Issued: June 15, 2004) :

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and Trademark Office due to an error which appears in the printed patent as a result of Patent and Trademark Office mistake and mistakes of a minor nature which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC_MAIN 174285v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,750,946 B2

DATED : June 15, 2004

INVENTOR(S): Yutaka TANAKA et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 4, "load-jock" should read -- load-lock --.

OLUMN 11:

Line 49, "the exposure" should read -- an exposure --. Line 50, "comprising" should read -- comprising: --.

COLUMN 12:

Line 61, "comprising" should read -- comprising: --.

COLUMN 14:

Line 6, "comprising" should read -- comprising: --.

COLUMN 15:

Line 9, "the exposure" should read -- an exposure --. Line 10, "comprising" should read -- comprising: --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,750,946 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

